

U.S. PUBLIC LAND SURVEY MONUMENT RECORD
CITY OF MEQUON 125

QUARTER SECTION CORNER $\begin{array}{|c|c|} \hline 18 & 18 \\ \hline 19 & 19 \\ \hline \end{array}$ TOWN 9 NORTH, RANGE 22 EAST
CITY OF MEQUON, OZAUKEE COUNTY

WISCONSIN STATE PLANE COORDINATES: NORTH 457,294.90
EAST 2,550,529.65

THETA ANGLE + 1-25-11 ELEVATION OF CORNER: _____

HORIZONTAL DATUM: WISCONSIN STATE PLANE SYSTEM, SOUTH ZONE
NORTH AMERICAN DATUM 1927 ADJUSTMENT
VERTICAL DATUM: MEAN SEA LEVEL 1929 ADJUSTMENT

HORIZONTAL CONTROL ACCURACY: 3RD ORDER, CLASS 1
VERTICAL CONTROL ACCURACY: 2ND ORDER, CLASS 2 MONUMENT NO. 90

DESCRIPTION OF MONUMENT: FOUND FOUR CONCRETE MONUMENTS WITH BRASS CAPS
IN HANDHOLES, WHICH WERE SET BY CLARENCE H. PIEPENBURG, S-139, IN AUGUST 1969,
WHICH ARE WITNESS MONUMENTS TO THE ACTUAL CORNER LOCATION, WHICH FALLS IN A
SANITARY SEWER MANHOLE. BRASS CAP MISSING ON MONUMENT 5' WEST OF CORNER LOCATION.
MONUMENT 5' SOUTH OF CORNER LOCATION IN POOR CONDITION. USED THE FOUR WITNESS
MONUMENTS, PLUS ONE WITNESS TIE FROM AUGUST 1969, AND A WITNESS TIE FOUND FROM
AN OLD UNDATED BADGER SURVEYING CO. FIELD NOTE TO REESTABLISH CORNER LOCATION
ON THE MANHOLE. ACCEPTED THIS LOCATION AS CORRECT AND REPLACED THE FOUR CONCRETE
MONUMENTS WITH TWO BERNTSEN W-1-B ALUMINUM MONUMENTS, ONE BEING PLACED 5'
NORTH AND ONE 5' EAST OF ACTUAL CORNER LOCATION, AND REFERENCED THE SAME AS
SHOWN HEREON. ALSO WOULD LIKE TO NOTE THAT OLD UNDATED BADGER SURVEYING CO.
FIELD NOTE SHOWED A LIMESTONE MONUMENT MARKING CORNER LOCATION. LIMESTONE
MONUMENT LIKELY WAS DESTROYED BY SANITARY SEWER CONSTRUCTION.

CERTIFICATION

I certify that the corner location on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.



SIGNATURE Thomas J. Genske S-1317 DATE: 6/28/94
Ozaukee County Surveyor

